



REPLACEMENT PARTS DM220ASS				
ITEM	PART NO	DESCRIPTION	QTY	PRICE
1	DB20281	Button Spring	2	\$3.63
2	DM25153SSM	2" Male Handle	1	\$57.29
3	DM220CAP	Dust Cap	1	\$80.30
4	DM25151SS	Stem	1	\$60.28
5	DM25155SS	Male Handle Interlock	1	\$50.33
6	DM25204SS*	Body Shim	1	\$11.73
7	DM25254MSS	Body	1	\$778.66
8	DM25255SSH	Ball	1	\$191.20
9	DM25256SS	End Plate	1	\$159.93
10	DM25288MSS	Safety Button	1	\$18.90
11	VSS15020	5/8" - 20 Jam Nut	1	\$2.36
12	VSS15021	5/8" Lock Washer	1	\$2.36
13	VSS15060*	Stem Packing	1	\$1.89
14	VSS15159	Packing Nut	1	\$16.83
15	VSS15160*	Stem Shim	1	\$6.27
16	DM25258FV1*	Filled Valve Body Seat	1	\$124.64
17	DM25258FV2*	Filled Valve End Plate Seat	1	\$131.68
18	DM221SS	Repair Kit	1	\$276.85

REPLACEMENT PARTS DM220DSS				
ITEM	PART NO	DESCRIPTION	QTY	PRICE
2	DB20281	Button Spring	2	\$3.63
3	DM220PL	Dust Plug	1	\$73.51
4	DM25001	Seal Ring	1	\$10.00
5	DM25002	Snap Ring	1	\$29.40
6	MLS234G	EPDM 234 O-Ring (old style)	1	\$1.81
6	MLS234GV*	FKM (viton type) 234 O-Ring (old style)	1	\$6.56
6	DM25294	2" FP FKM(viton type) Face Seal (new style)	1	\$43.70
6	DM25294T	2" FP Kalrez® Face Seal	1	\$1,421.94
7	DM25004	Groove Pin	2	\$11.23
8	DM25009	Clamp Arm	2	\$30.28
9	DM25010	Clamp Lever (old style)	2	\$30.28
9	DM25010A	Clamp Lever (new style)	2	\$40.26
10	DM25151SS	Stem	1	\$60.28
11	DM25153SSF	Female Handle	1	\$57.29
12	DM25154SS	Female Handle Interlock	1	\$55.61
13	DM25204SS*	Body Shim	4	\$11.73
14	DM25254FSS	Body	1	\$948.48
15	DM25255SSH	Ball	1	\$150.63
16	DM25256SS	End Plate	1	\$159.93
17	DM25258FV1*	Filled Valve Body Seat PTFE	1	\$124.64
18	DM25258FV2*	Filled Valve Body Plate Seat PTFE	1	\$131.68
19	DM25288FSS	Interlock Button	1	\$18.90
20	DM25289SS	Locking Yoke	1	\$96.89
21	VSS15020	5/8" - 20 Jam Nut	1	\$2.36
22	VSS15021	5/8" Lock Washer	1	\$2.36
23	VSS15060*	Stem Packing	1	\$1.89
24	VSS15159	Packing Nut	1	\$16.83
25	VSS15160*	Stem Shim	1	\$6.27
26	DM25018	Cam Lever Pin (old style)	4	\$13.96
26	DM25018A	Cam Lever Pin (new style)	4	\$8.84
27	DM25020	#10-24 x 5/16" Set Screw	4	\$6.57
N/S	DM222SS	Repair Kit	1	\$360.80

Valve repair kits contain items marked with asterisk *.