

M9104-100 Conduit Adapter

Packing Slip

M9104-100

Part No. 34-1723-1, Rev. —
Release May 8, 2007

Installation

This procedure describes the recommended method to install the M9104-100 Conduit Adapter used with the M9104 Series Electric Actuators.

Parts Included

- One M9104-100 Conduit Adapter
- One #10-14 x 1/2 in. thread forming Plastite® screw with Torx® head/slotted pan head (installed in conduit adapter)
- One #3-24 x 1/2 in. thread forming Plastite screw with cross-recessed pan head

Special Tools Needed

- No. 1 Phillips screwdriver
- T-20 Torx head driver or 3/8 in. wide flathead screwdriver

Installing the Conduit Adaptor

1. Remove the rear cover screw from the actuator and discard.




Figure 1: Removing the Rear Cover Screw

2. Install the conduit adapter over the screw hole in the actuator cover.
3. Use the supplied #3-24 x 1/2 in. screw to fasten the conduit adapter to the actuator.




Figure 2: Installing the M9104-100 Conduit Adapter



Controls Group
507 E. Michigan Street
Milwaukee, WI 53202

*Metasys® is a registered trademark of Johnson Controls, Inc.
All other marks herein are the marks of their respective owners.
© 2007 Johnson Controls, Inc.*